

JARGY CO., LTD.

Test Report

Model :CBL-D302MBS-10m

Ver : 1.0

Date : 2017/9/11

Camera Brand Name : **Toshiba Teli**


Test Platform

| | | | |
|----------------|---|--|--|
| Type | USB3 CAM Control System | | |
| Model | Advantech AIIS-1440 | | |
| OS | Windows 7 Pro 64-bit | | |
| CPU | Intel Core i7-3770 | | |
| HDD | SATA III 500GB | | |
| RAM | DDR3 16GB | | |
| USB 3.0 | Dedicated controller 4 Ports (uPD720202) | | |

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Tested Camera : **BU302MCF** (2048 x 1536, 3.15MP, 2.3MP, 165fps, 380MB/s) + **DU657MC** (2560 x 2560, 6.5MP, 55fps, 360MB/s)

Tested time :**168h**



DU657MC

BU302MCF

TeliU3vViewer

Camera Image Control Tool View Help

[Cap = 55.56 fps] View option

DU657MC

ImageFormatControl

PixelFormat: BayerGR8 Bitshift (for Viewer): 0

PixelCoding: BayerGR Bayer convert (for Viewer):

PixelFormatSize: Bpp8

OffsetX: 0

OffsetY: 0

Width: 2560

Height: 2560

ImageFormatSelector: Format0

BinningHorizontal: 0

BinningVertical: 0

Acquisition Control

AcquisitionFrameRateControl: NoSpecify

AcquisitionFrameRate (Hz): 55.908 Min=0.488 Max=55.908

DriverSetting (SDK): MaxPacketSize: 65536

CameraName: DU657MC - 0100040

Log

| Date (M/D H:M:S) | Type | Code | Area | Message |
|------------------|------|------------|------------|-----------|
| 9/04 08:40:56 | Info | 0x00000000 | Image | SIPayload |
| 9/04 08:40:56 | Info | 0x00000000 | Image | SIPayload |
| 9/04 08:40:56 | Info | 0x00000000 | Image | SIPayload |
| 9/04 08:40:56 | Info | 0x00000000 | Image | SIPayload |
| 9/04 08:40:56 | Info | 0x00000000 | Main Frame | Camera |
| 9/04 08:40:58 | Info | 0x00000000 | Main Frame | Grab Star |

TeliU3vViewer

Camera Image Control Tool View Help

[Cap = 120.02 fps] View option

BU302MCF

ImageFormatControl

PixelFormat: BayerBG8 Bitshift (for Viewer): 0

PixelCoding: BayerBG Bayer convert (for Viewer):

PixelFormatSize: Bpp8

OffsetX: 0

OffsetY: 0

Width: 2048

Height: 1536

ImageFormatSelector: Format0

BinningHorizontal: 0

BinningVertical: 0

Acquisition Control

AcquisitionFrameRateControl: NoSpecify

AcquisitionFrameRate (Hz): 120.056 Min=0.488 Max=120.056

DriverSetting (SDK): MaxPacketSize: 65536

CameraName: BU302MCF - 0500010

Log

| Date (M/D H:M:S) | Type | Code | Area | Message |
|------------------|------|------------|------------|------------|
| 09/04 08:41:18 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:18 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:18 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:18 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:18 | Info | 0x00000000 | Main Frame | Camera O |
| 09/04 08:41:20 | Info | 0x00000000 | Image | PixelCodin |
| 09/04 08:41:20 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:20 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:20 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:20 | Info | 0x00000000 | Image | SIPayload |
| 09/04 08:41:22 | Info | 0x00000000 | Main Frame | Grab Star |

上午 09:25
2017/9/11